

1/28




FIG.1

FIG. 1 is a block diagram of a glass powder production system.

FIG. 2

3/28




FIG.3

4/28




FIG. 4




FIG. 5

5/28




FIG. 6




FIG. 7

10032298.122101

6/28




FIG.8

7/28




FIG.9




FIG.10

10032293-123404

8 / 28




FIG. 11

100-202920-11

9/28




FIG.12

FIG. 12

10/28




FIG.13




FIG.14

11/28




FIG. 15




FIG. 16

FIG. 15

12/28




FIG.17

FIG. 17




FIG. 18




FIG. 19

FIG. 18

14/28




FIG.20




FIG.21

FIG. 22 "SECRET"




FIG.22

FIG. 22 is a flowchart of a glass powder production process.

16/28




FIG.23

17/28




FIG.24

100338-123401

18/28




FIG.25

10032298.122104

19/28




FIG. 26




FIG. 27

20/28




FIG.28

FIG. 28 is a flowchart of the process for producing glass powder.

21/28




FIG.29




FIG.30




FIG.31

11032298-122101

22/28




FIG.32

FIG. 32




FIG.33

FIG. 33 is a schematic diagram of a glass powder processing system.

24/28




FIG.34

FIG. 34 "SECRET"

25/28




FIG. 35A




FIG. 35B




FIG. 35C




FIG. 35D




FIG. 35E




FIG. 35F

FIG. 35A

26/28





FIG.36

FIG. 36

27/28



10032298 122101

FIG.37

28/28

